

# PROACTIVE STEPS FOR FACILITY MAINTENANCE

# COMPLY

Implement and ensure compliance with your Falls Management Program (FMP).



# **COMPLETE**

Complete a broad Living Space Inspection (LSI) to identify risk factors.



#### **ASSIGN**

Assign a Falls Engineer to complete an Engineer Inspection List.





# **CURTAINS**

Utilize tiebacks for divider curtains to clear resident pathways to reduce risks of entanglement and fall hazards.



## **HANDRAILS**

Inspect hallway handrails to ensure comfortable, ADA compliant grip.



## **BATHROOMS**

Install grab bars, secure loose bathroom handrails.



#### **FLOORING**

Repair or replace flooring in hallways and entranceways to reduce risks of falls due to wet or slippery surfaces.

Acrovyn® Wall Protection offers extensive, durable product options that are

ideal for healthcare and senior living facilities. Our attractive, ergonomically designed handrails promote mobility and stability for those who need it. For more product information, visit our website, call 800.304.2234 or email seniorliving@c-sgroup.com.

Agency for Healthcare Research and

Sources: