

STYX™

Care and Maintenance

Storage

1. Protect materials from physical damage. It is best to keep them stored in their original crating and packaging in a dry, well-ventilated location free from dirt and debris.
2. Store materials to allow for inspection and measurement of quantity and size units.
3. Handling of the materials shall be kept to a minimum.

Handling / Maintenance

STYX systems are virtually maintenance free. To maintain the appearance and structural integrity of the system, the following procedures should be performed at least once per year, or more frequently if needed.

1. Visually inspect the system for any apparent defects, loose fasteners, etc.
2. Remove any debris that may have accumulated on the system.
3. Wipe down the system with clean water.
4. Using a non-abrasive device, wash the system with a mild soapy mixture and rinse with clean water. Do not use abrasive cleaners, Scotch-Brite™, Brillo®, S.O.S® pads or steel wool on any metal.
5. Inspect all fasteners. Check the recommended torque settings on the bolt and nut connections that fasten the system to the mounting rails.