



5 Common Issues with *Existing Expansion Joint Covers*



Warping

Due to:

- Incorrect cover was specified (standard vs. heavy duty)
- Point load considerations were exceeded by cranes, carts, cars, cleaning equipment, etc.



Cracked Finishes

Due to:

- Improper installation of cover assembly or adjacent finishes
- Building movement was exceeded
- Loading capabilities were exceeded



Tripping Hazard

Due to:

- Improper installation
- Building movement was exceeded
- Damaged cover
- Building settlement



Excessive Noise

Due to:

- Damage or absence of internal gasket
- Improper installation
- Loosening screws
- Warping



Leaking Water

Due to:

- Absence of moisture barrier
- Poor blockout conditions
- Excessive water loads
- Improper installation
- Bad splice

**Need to replace your
damaged expansion
joint cover?
Contact us!**



Construction Specialists®

c-sgroup.com | 800.233.8493
©2025 Construction Specialists, Inc.